

Инв. N подл.	Погр. и дата	Взам. инв. N
R4.05270.4.0.32		

Ряды зажимов шкафа N107 ПАА ВЛ 220 кВ
WE03 РП "Волгодонск" (II цепь)

Левая боковина

Цепи АПАР линии WE03				02
01x5	x1'	1	x2	2SG1/2
01x6	x2'	2	x3	2SG1/6
01x7	x3'	3	x4	2SG1/10
01x4	x4'	4	x5	2SG1/12
		5	x6	2SG1/8
		6		2SG1/4
		7		
		8	x6	2SG1/14
		9	x9	2SG1/16
		10		
01x15	x11'	11	x11	2SG2/2
01x16	x12'	12	x12	2SG2/6
01x17	x13'	13	x13	2SG2/10
		14		
A428		15	x15	2SG2/4
B428		16	x16	2SG2/8
C428		17	x17	2SG2/12
		18	x18	2SG2/14
		19	x19	2SG2/16
		20		
Цепи переменного напряжения АПАР линии WE03				02
A722-WE03		x21	x21	2SA1.4:1
B722-WE03		x22	x22	2SA1.4:5
C722-WE03		x23	x23	2SA1.4:9
N722-WE03		x24	x24	2SA1.4:13
2SA1.4:2	x25'	25	x25	2SG3/2
2SA1.4:6	x26'	26	x26	2SG3/4
2SA1.4:10	x27'	27	x27	2SG3/6
2SA1.4:14	x28'	28	x28	2SG3/8
A721		x29	x29	2SA1.4:4
B721		x30	x30	2SA1.4:8
C721		x31	x31	2SA1.4:12
N721		x32	x32	2SA1.4:16
		33		
H722-WE03		x34	x34	2SA1.4:17
K722-WE03		x35	x35	2SA1.4:21
F722-WE03		x36	x36	2SA1.4:25
U722-WE03		x37	x37	2SA1.4:29
2SA1.4:18	x38'	38	x38	2SG4/2
2SA1.4:22	x39'	39	x39	2SG4/4
2SA1.4:26	x40'	40	x40	2SG4/6
2SA1.4:30	x41'	41	x41	2SG4/8
H721		x42	x42	2SA1.4:20
K721		x43	x43	2SA1.4:24
F721		x44	x44	2SA1.4:28
U721		x45	x45	2SA1.4:32
Оперативные цепи АПАР линии WE03				02
hu201-WE03		x46	x46	A2: X1/1
		x47	x47	E1:1
		x48	x48	A2: X6.2/7
		x49	x49	A2: X6.2/9
		x50	x50	A2: X6.2/11
		x51	x51	A2: X6.3/1
		x52	x52	A2: X6.3/3
		x53	x53	A2: X6.3/5
		x54	x54	A2: X6.3/7
		x55	x55	A2: X6.3/9
		x56	x56	A2: X6.3/11
		x57	x57	A2: X6.4/1
		x58	x58	A2: X6.4/3
		x59	x59	A2: X6.4/5
		x60	x60	A2: X6.4/7
		x61	x61	A2: X6.4/9
		x62	x62	A2: X6.4/11
		63		
		64		
hu202-WE03		x65	x65	A2: X1/2
		x66	x66	E1:2
		x67	x67	A2: X6.2/8
		x68	x68	A2: X6.2/10
		x69	x69	A2: X6.2/12
		x70	x70	A2: X6.3/2
		x71	x71	A2: X6.3/4
		x72	x72	A2: X6.3/6
		x73	x73	A2: X6.3/8
		x74	x74	A2: X6.3/10
		x75	x75	A2: X6.3/12
		x76	x76	A2: X6.4/2
		x77	x77	A2: X6.4/4
		x78	x78	A2: X6.4/6
		x79	x79	A2: X6.4/8
		x80	x80	A2: X6.4/10
		x81	x81	A2: X6.4/12
		82		
		83		
		84		
		85		
Выходные цепи АПАР линии WE03				02
1-AE05A		x86	x86	2SA1.1/5
1-AE05A		x87	x87	2SA1.1/21
1-AE90A		x88	x88	2SA1.1/8
1-AE90A		x89	x89	2SA1.1/24
		90		
37-AE05A		x91	x91	2SA1.1/24
37-AE90A		x92	x92	2SA1.1/24
51-AE05A		x93	x93	2SA1.1/24
70-AE90A		x94	x94	2SA1.1/24
		95		
		96		
1-1-AE05A		x97	x97	2SA1.1/134
1-1-AE90A		x98	x98	2SA1.1/16
		99		
1-37-AE05A		x100	x100	2SA1.1/17
1-37-AE90A		x101	x101	2SA1.1/20
		102		
n3009		x103	x103	A2: X5.1/4
		104		
n3111		x105	x105	2SA1.2/4
		106		
		x107	x107	A2: X5.1/5
		x108	x108	A2: X5.1/6
		x109	x109	A2: X5.3/1
		x110	x110	A2: X5.3/2
		x111	x111	A2: X5.3/3
		x112	x112	A2: X5.3/4
		x113	x113	A2: X5.3/5
		x114	x114	A2: X5.3/6
		x115	x115	A2: X5.5/1
		x116	x116	A2: X5.5/2
		x117	x117	A2: X5.5/3
		x118	x118	A2: X5.5/4
		x119	x119	A2: X5.5/5
		x120	x120	A2: X5.5/6
		121		
		x122	x122	2SA1.2/5
		x123	x123	2SA1.3/4
		x124	x124	2SA1.3/5
		x125	x125	A2: X5.4/2
		x126	x126	A2: X5.4/3
		x127	x127	A2: X5.4/4
		x128	x128	A2: X5.4/5
		x129	x129	A2: X5.4/6
		x130	x130	A2: X5.6/1
		x131	x131	A2: X5.6/2
		x132	x132	A2: X5.6/3
		x133	x133	A2: X5.6/4
		x134	x134	A2: X5.6/5
		x135	x135	A2: X5.6/6
		136		
		137		
		138		
		139		
		140		
Проходные клеммы				02
		x141		
		x142		
		x143		
		x144		
		x145		
		x146		
		x147		
		x148		
		x149		
		x150		
		x151		
		x152		
		x153		
		x154		
		x155		
		x156		
		x157		
		x158		
		x159		
		x160		
		x161		
		x162		
		x163		
		x164		
		x165		
		x166		
		x167		
		x168		
		x169		
		x170		
		x171		
		x172		
		x173		
		x174		
		x175		
		x176		
		x177		
		x178		
		x179		
		x180		
		x181		
		x182		
		x183		
		x184		
		x185		
		x186		
		x187		
		x188		
		x189		
		x190		
		x191		
		x192		
		x193		
		x194		
		x195		
		x196		
		x197		
		x198		
		x199		
		x200		
Цепи ~220 В				00
A		1	00x	SF1/1
		2		
		3		
N		4	00x	SF1/3
		5		

Правая боковина

Клемма Weidmüller WPL 6/3/STB	01				Цепи тока АОПО линии WE03				01			
	1SG1/2	x1	1					A461a-WE03				
	1SG1/6	x2	2					B461a-WE03				
	1SG1/10	x3	3					C461a-WE03				
	02x4	x4	4					N461a-WE03				
	1SG1/4	x5	5	x5'					02x1			
	1SG1/8	x6	6	x6'					02x2			
	1SG1/12	x7	7	x7'					02x3			
	1SG1/14	x8	8									
	1SG1/16	x9	9									
			10									
	1SG2/2	x11	11					A427				
	1SG2/6	x12	12					B427				
	1SG2/10	x13	13					C427				
			14									
	1SG2/4	x15	15	x15'					02x11			
	1SG2/8	x16	16	x16'					02x12			
	1SG2/12	x17	17	x17'					02x13			
	1SG2/14	x18	18									
	1SG2/16	x19	19									
		20										
Клемма Weidmüller WPL 6/3/STB	01				Цепи переменного напряжения АОПО линии WE03				01			
	1SG3/2	x21	21									
	1SG3/4	x22	22									
	1SG3/6	x23	23									
	1SG3/8	x24	24									
			25									
	01				Оперативные цепи АОПО линии WE03				01			
	A1: X1/1	x26	26	?				hu101-WE03				
			27	?								
	A1: X6.2/11	x28	28									
	A1: X6.3/1	x29	29									
	A1: X6.3/3	x30	30									
	A1: X6.3/5	x31	31									
	A1: X6.3/7	x32	32									
	A1: X6.3/9	x33	33									
	A1: X6.3/11	x34	34									
			35									
			36									
	A1: X1/2	x37	37	?				hu102-WE03				
			38	?								
A1: X6.2/12	x39	39										
A1: X6.3/2	x40	40										
A1: X6.3/4	x41	41										
A1: X6.3/6	x42	42										
A1: X6.3/8	x43	43										
A1: X6.3/10	x44	44										
A1: X6.3/12	x45	45										
		46										
		47										
		48										
		49										
		50										
Клемма Weidmüller WPL 6/3/STB	01				Выходные цепи АОПО линии WE03				01			
	A1: X5.1/1	x51	51									
	A1: X5.1/2	x52	52									
	A1: X5.1/6	x53	53					161				
			54									
	1SA1.3/4	x55	55					3-AE80A				
	A1: X5.3/1	x56	56									
	A1: X5.3/2	x57	57									
	A1: X5.3/3	x58	58									
	A1: X5.3/4	x59	59									
	A1: X5.3/5	x60	60									
	A1: X5.3/6	x61	61									
	A1: X5.5/1	x62	62									
	A1: X5.5/2	x63	63									
	A1: X5.5/3	x64	64									
	A1: X5.5/4	x65	65									
	A1: X5.5/5	x66	66									
	A1: X5.5/6	x67	67									
			68									
	1SA1.1/4	x69	69									
1SA1.1/5	x70	70										
1SA1.3/5	x71	71										
1SA1.4/4	x72	72										
1SA1.4/5	x73	73										
1SA1.5/4	x74	74										
1SA1.5/5	x75	75										
1SA1.6/4	x76	76										
1SA1.6/5	x77	77										
A1: X5.6/2	x78	78										
A1: X5.6/3	x79	79										
A1: X5.6/4	x80	80										
A1: X5.6/5	x81	81										
A1: X5.6/6	x82	82										
		83										
1SA1.2/5	x84	84	?				1-AE08A					
1SA1.2/21	x85	85	?									
1SA1.2/8	x86	86	?				1-AE90A					
1SA1.2/24	x87	87	?									
		88										
1SA1.2/9	x89	89					33-AE08A					
1SA1.2/12	x90	90					37-AE90A					
1SA1.2/25	x91	91					70-AE08A					
1SA1.2/28	x92	92					70-AE90A					
		93										
1SA1.2/13	x94	94					1-1-AE08A					
1SA1.2/16	x95	95					1-1-AE90A					
		96										
1SA1.2/17	x97	97					1-33-AE08A					
1SA1.2/20	x98	98					1-37-AE90A					
		99										
		100										
		101										
		102										
		103										
		104										
		105										
		106										
		107										
		108										
		109										
		110										
		111										
		112										
		113										
		114										
		115										
		116										
		117										
		118										
		119										
		120										
		121										
		122										
		123										
		124										
		125										
		126										
		127										
		128										
		129										
		130										
		131										
		132										
		133										
		134										
		135										
		136										
		137										
		138										
		139										
		140										
		141										
		142										
		143										
		144										
		145										
		146										
		147										
		148										
		149										
		150										
Клемма Weidmüller WPL 6/3/STB	00				Цепи сигнализации				00			
	SA1/1	x6	6	?				+EH-WE03				
			7	?								
			8									
	A1: X3/1	x9	9	?	x9'			SA1/2				
	A2: X3/1	x10	10	?								
			11									
	1KH1/5	x12	12					WE03E905				
	1KH2/5	x13	13					WE03E903				
	2KH1/5	x14	14					WE03E1039				
	2KH2/5	x15	15					WE03E1021				
			16									
	SA1/4	x17	17	?				-EH-WE03				
			18	?								
	SA1/3	x19	19	?								
	HL1	x20	20	?	x20'			1KH1/2				
			21									
	1KH1/4	x22	22									
	2KH1/4	x23	23									
	1KH2/4	x24	24	?				01-501				
2KH2/4	x25	25	?									
		26										
1KH1/6	x27	27										
2KH1/6	x28	28										
1KH2/6	x29	29					01-569					
2KH2/6	x30	30					01-571					
		31										
SA2/1	x33	33					PG300-WE03					
		34										
A1: X3/3	x35	35	?				PG301					
		36	?									
A1: X3/5	x37	37										
A1: X4/3	x38	38	?				PG302					
		39	?									
A1: X4/5	x40	40										
A2: X3/3	x41	41	?				PG303					
	x42	42	?									
A2: X3/5	x43	43										
A2: X4/3	x44	44	?				PG304					
	x45	45	?									
A2: X4/5	x46	46										
		47										
		48										